

PART OF THE EXCAVATION OF THE VICTORIAN GLASSHOUSE

Remains of a plinth that supported a bench or table with mortar on top showing the original would have been higher

Base of slate water tank. The sides were about 50cms tall. There is a drain in the right hand corner

Remains of a partition wall inside the glasshouse

Clay drainage pipes at the bottom of the trench.

Thin lead pipe, hollow, of uncertain purpose.

19th century cast iron pipe - probably taking hot water round the glasshouse at just above floor level

